

## CARE IN STORAGE AND HANDLING

SOLUS products must be stored in appropriate conditions to ensure their physical and visual characteristics until the moment of their use. Pay attention to the following conditions:

- **Do not store for very long periods.** Use the product preferably up to 06 (six) months after its manufacture. This avoids tonality changes, embossing and malleability.
- **Keep the material packed, even when fractionated.** This prevents the action of moisture and changes in the physical and visual characteristics of the product.
- **Keep the product in an environment with air humidity around 60%** (neither too humid nor too dry). This prevents changes in flexibility, elasticity and tear resistance, as well as the appearance of mold.
- **Avoid exposure to sunlight,** preferably by keeping the material covered. This avoids possible color changes.
- **Keep the temperature of the storage place around 25°C.** Avoid very high or very low temperatures, as there may be a change in product dimensions, thickness, malleability and flexibility.
- **Store the coils in an upright position.** They should not be stacked, so that there is no deformation or marks on the product.
- **Keep the plates in the horizontal position,** preferably on the source pallet.
- **Pay special attention to the care of products in light colors.** They can smudge more easily and there can be micro-cracking in the embossing underneath.
- **The handling and application of the products must be done in a clean place,** with hands, tools and equipment also being clean.


## CARE IN USE AND CONSERVATION

The conservation of SOLUS products must be done in an appropriate manner to ensure their characteristics and the expected result. Pay attention to the following conditions:

- To remove spilled liquids, immediately use a high absorption paper. If there is still a need to clean the surface, use a soft cloth, slightly moistened with water and mild soap.
- Avoid contact with any type of cleaning chemical such as bleach, alcohol, solvents, silicones, removers or polishers.
- Never use an abrasive sponge or steel straw. Avoid scraping the surface with sharp, pointed or rough accessories or objects as they may cause scratches or marks.
- Direct exposure to sunlight or powerful light bulbs, as well as weather conditions. This can alter the visual characteristics and shorten the life of the product.

**Due to the naturalness of the product and its production process, small variations in color, brightness, texture (embossing) and thickness between batches may occur.**

 @solusnaturalmente

 +55 51 2101.1900

 [www.soluscoureconstituído.com.br](http://www.soluscoureconstituído.com.br)



Access the QR Code

A COMPANY OF  
**MK**  
GRUPO

**SOLUS**  
NATURALLY